

APPENDIX B

► INSTALLATION ENVIRONMENTAL RESTORATION DOCUMENTS SUMMARY TABLES ◀

This page intentionally left blank.

TABLE B-1. PROJECT DELIVERABLES

Year	Phase	Project Title	Report No.	Sites Examined	Contractor/Delivery Date
1987	PA	RCRA Facility Assessment	1	1-30	NUS Corporation, June 1987
1990	ENPA	Enhanced Preliminary Assessment	2	1-82	Dames & Moore, April 1990
1992	RA	Risk Assessment for Explosive Washout Lagoons	3	4	Dames & Moore, April 1992
1992	RI	Remedial Investigation/ Alternatives	4	4	Dames & Moore, April 1992
1992	FS	Feasibility Study	5	58 sites	Dames & Moore, August 1992
1992	RA	Human Health Baseline Risk Assessment	6	58 sites	Dames & Moore, August 1992
1993	SRI	Supplementary Remedial Investigation	12	13 sites	Dames & Moore, September 1993
1993	RA	Supplementary Human Health Baseline Risk Assessment	13	13 sites	Dames & Moore, September 1993

TABLE B-2. SITE DELIVERABLES

Site ID	ENPA/SI	RI/FS	RD/RA	Close Out	IRA	LTM	NFRAP
OU 1	2	5					
OU 2	2	4,5					
OU 3	2	5					
OU 4	2	5					
OU 5	2	5					
OU 6	2	5					
OU 7	2	5					10
OU 8	2	5					11
OU 9	2	5					18

Note: Numbers refer to report numbers listed in Table B-1, Project Deliverables.

**TABLE B-3. TECHNICAL DOCUMENTS/
DATA LOADING STATUS SUMMARY**

Date	IRP Title	Site/OU	Contractor	Service Center	IRDMIS Status/Other
	Technical documents/data loading status summary will be provided in later versions of the BCP.				